

LINDSAY CREEK CULVERT REPLACEMENT



Upstream View before Construction



Debris Dam in inlet and Deteriorated Condition of Culvert

LINDSAY CREEK CULVERT REPLACEMENT



View Towards Inlet



Outlet View from Downstream

LINDSAY CREEK CULVERT REPLACEMENT



Fish Removal by Tetra Tech and CDFG



Plunge Pool was drawn Down Slightly to Facilitate Electro Fishing

LINDSAY CREEK CULVERT REPLACEMENT



Waterline Suspended above Excavation



Creek Flow was Pumped around the Project

LINDSAY CREEK CULVERT REPLACEMENT



Excavation Prior to Placement of Temporary Flatcar Bridge



Temporary Flatcar Bridge Viewed from Downstream

LINDSAY CREEK CULVERT REPLACEMENT



River Gravel Stream Channel Backfill



Assembly of Arch Panels

LINDSAY CREEK CULVERT REPLACEMENT



Bolt Tightening and Backfill



Outlet Rip Rap before Being Concreted

LINDSAY CREEK CULVERT REPLACEMENT



Inlet Rip Rap before Being Concreted



Upstream View at Completion of Project

LINDSAY CREEK CULVERT REPLACEMENT



Inlet, Photograph taken 03-08-02



Outlet, Photograph taken 03-08-02