


CONNER CREEK

Migration Barrier Removal Project
Red Hill Road

Trinity County

July-September 2012

CONTEXT

































Design Elements









BMPs



EROSION REPAIR AND CONTROL 3-A-2



Figure 1. Properly installed straw bale and construction of straw bale barrier.





Figure 2. Semi-pervious straw bale sediment barrier, with sand and gravel spillway.































Site Characteristics







Staging Areas













INNOVATION





























Problems



















Questions?

